Caltrans | EXPLORATION BORING FIELD LOG | Date 4/09/08 | Boring No. RW11-A1

Location Doyle Drive Replacement | Log No. | EA No. 163701 | Page 1 of 3

Dist. 04 Co. SF Rt. 101 P.M. Br. No. Purpose of Work Geotechnical Investigation

Rt. Ft.. Lt. Line. Sta. Northings. Eastings. Elev. 11.232

Ground Water Data: Date/Time | Water Level | Bot. of Boring

Logged By : E. Ortega | Drill Crew : Brad Johnson

Drill rig : CME 75 | Hammer Type and Weight :

Drilling Method : Rotatory Wash | Casing :

Hole Completion : 4/10/08

Depth	Sample Interval	Tool	Blows RQD	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Remarks
1								← Drilled thru unpaved area	Corrosion Sample
2									
3									
4									
5									
6		0	Push					Sandy fat clay (CH), very soft, dark gray, moist, high pls $q_u = 2.75$ Ton/ft2	
7									
8									
9									
10		0	Push					Poorly graded sand with silt (SP-SM), very loose, dark gray, moist, low pls, med. sand, weak cementation	
11									
12									
13									
14									
15		6						Poorly graded sand (SP), med dense, dark gray, moist, n.pls, med sand, weak cementation, with marine shells	
16		5							
17		6							
18									
19									
20								Same	
21		10							
22		15							
23		9							
24									
25									
26									
27									
28									
29									
30		0	Push					Poorly graded sand with silt (SP-SM), very loose, dark gray, moist, low pls, med. sand, weak cementation	
31									
32									
33									
34									
35									
36									
37									
38									
39									
40									

Caltrans | EXPLORATION BORING FIELD LOG

Date 4/9/08 to 4/10/08 | Boring No. RW11-B1

Location Doyle Drive Replacement | Log No. | EA No. 163701 | Page 2 of 3

Dist. 04 Co. SF Rt. 101 P.M. | Br. No. | Purpose of Work Geotechnical Investigation

Ft. Rt. Lt. | Line. Sta. | Northings. | Eastings. | Elev.

Ground Water Data: Date / Time | Water Level | Bot. of Boring

Logged By: E. Ortega | Drill Crew: Brad Johnson

Drill rig: CME 75 | Hammer Type and Weight:

Drilling Method: Rotatory Wash | Casing:

Hole Completion: 4/10/08

Depth	Sample Interval and Type	Tool	Blows/6"	RQD	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Remarks
21			6						Same with marine shell	
22										
23										
24										
25			11						Same but dense	
26			19							
27			20							
28										
29										
30			13						Colma Sand, Poorly graded sand (SP), dense, light brown, moist, fine to med. sand, weak cementation, with oxidation spots	
31			20							
32			22							
33										
34										
35										
36										
37										
38										
39										
40										
41			9							
42			23							
43			23							
44										
45										
46									Same	
47										
48										
49										
50									Same	
51			19							
52			25							
53			21							
54										
55										
56										
57										
58										
59										
60			4						Gix upper - Same Marin Sedimentary gravelly fat Clay (CH), hard, dark gray, thick pls with 5% gravels to 2"	
61			9							
62			35							
63										
64										
65										

Caltrans | EXPLORATION BORING FIELD LOG | Date 4/10/08 | No. RW11-A1

Location: Doyle Drive Replacement | Loc No. | EA No. 163701 | Page 3 of 3

Dist. 04 Co. SF Rt. 101 P.M. Br. No. | Purpose of Work: Geotechnical Investigation

Rt. Ft., Lt. Line, Sta. Northings. Eastings. Elev.

Ground Water Data: Date/Time | Water Level | Bot. of Boring

Logged By: E. Ortega | Drill Crew: Brad Johnson

Drill rig: CME75 | Hammer Type and Weight:

Drilling Method: Rotatory Wash | Casing:

Hole Completion: 4/10/08

Depth	Sample & Pocket Penetrometer	Blows/ft. or Core Run	RQD	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Remarks
59								Sedimentary rock, Sandstone decomposed to v. int fractured, dark gray	
60		>50						Sandstone, moderately to intensely fractured, dark/gray, soft with oxidation spots and calcium	
61								RQD = 4.5+11+4.5+14+4/54 = 62.5%	
62								Same but intensely to v. int fract	
63								RQD = 5+8+7+7/60 = 45%	
64									
65									
66									
67								Same but moderately to intensely fract	
68								RQD = 11+10+8+9+5.5+4.5+5/60 = 95.83%	
69									
70									
71									
72									
73									
74									
75								Bottom of boring @ 75 ft on 4/10/08	

RW11-A1

Caltrans | EXPLORATION BORING FIELD LOG | Date 12-13-07 | Boring No. ENB-R2

Location Doyle Drive Replacement | Lab No. | EA No. 163701 | Page 1 of 4

Dist. 04 Co. SF Rt. 101 P.M. Br. No. Purpose of Work Geotechnical Investigation

Ft., Rt. Lt. Line. Sta. Northings. Eastings. Elev. 11.8

Ground Water Data: Date / Time | Water Level | Bot. of Boring

Logged By : E Ortega | Drill Crew :

Drill rig : | Hammer Type and Weight :

Drilling Method : Wet rotatory | Casing :

Hole Completion : 12-14-07

Depth	Sample Interval / Tool / Blows	RQD	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Remarks
1							Drilled thru AC pavement	
2								
3	4							MC
	5							
4	8							
	3						Fill: Uniformly graded Sand (SP), loose, dark gray, moist, medium sand	SPT
5	3							
6	3							▽ Estimated
7								← Wet drill
8								
9								
10								← 9'8" start Bay Mud
11								Shelby 10'-12.5'
12								
13								
14								
15	0							
16	1	b						MC
	1	a						
17	1						← Poorly graded Silty Sand (SP-SM)	
	2						loose, dark gray, moisture, fine Sand	SPT
18	6							
19								
20								
21	5							MC
	15							
22	19	a						
23	1						← Same but medium dense	
	9							SPT
24	13							
25								

Caltrans | EXPLORATION BORING FIELD LOG | Date 12-13-07 | Boring No. ENB-R2

Location Doyle Drive Replacement | Lab No. | EA No. 163701 | Page 2 of 4

Dist. 04 Co. SF Rt. 101 P.M. | Br. No. | Purpose of Work Geotechnical Investigation

Ft.. Rt./Lt. | Line. Sta. | Northings. | Eastings. | Elev. 0'

Ground Water Data: Date/Time | Water Level | Bot. of Boring

Logged By : E. Ortega | Drill Crew :

Drill rig : | Hammer Type and Weight :

Drilling Method : Wet Rotatory | Casing :

Hole Completion :

Depth	Sample Interval	Tool	Blows	RQD	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Remarks
25										
			1							MC
26			0							
			1		a					
27			1						← Same, but loose	SPT
			3							
28			5							
29										
30			7							MC
			7							
31			11		a					
32			5						← Same, but medium dense and with marine shells.	SPT
			6							
33			7							
34										
35			25		b					MC
36			34		a					
			43							
37			19						← Uniform/graded Sand (SP), very dense, light brown, med sand some oxidation spots (Colma Sand)	SPT
			35							
38			49							
39										
40										
			26							MC
41			40							
			41		a					
42			16						← Same	SPT
			30							
43			33							
44										
45										
			23							MC
46			50		b					
					a					
47			17						← Same but dense	SPT
			43							
48			50		5.5"					

Caltrans

EXPLORATION BORING FIELD LOG

Date 12-13-07 | Boring No. ENB-R2

Location Doyle Drive Replacement | Lab No. | EA No. 163701 | Page 3 of 4

Dist. 04 Co. SF Rt. 101 P.M. | Br. No. | Purpose of Work Geotechnical Investigation

Rt. Ft., Lt. | Line, Sta. | Northings. | Eastings. | Elev.

Ground Water Data: Date/Time | Water Level | Bot. of Boring

Logged By: E Ortega | Drill Crew:

Drill rig: | Hammer Type and Weight:

Drilling Method: Wet rotatory | Casing:

Hole Completion:

Depth	Sample Interval	Core Blows/RQD	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Remarks
49								
50								
		21						MC
51		39	b					
		48	a					
52								
53								
54								
55								
		16					← Same, but very dense and	SPT
56		32					some marine shells	
		50	5"					
57								
58								
59								
60								
		18					← Poorly graded, Silty Sand (SP-SM)	MC
61		23					very dense, dark brown, medium sand	
		28	a					
62								
63								
64								
65								
		13					← Same	SPT
66		17						
		13					← Lean Clay (CL), very stiff,	
67							dark gray, low to medium plasticity	
68							q_u = 3.4 Tons/ft²	
69								
70								
		50	5"				← SEDIMENTARY ROCK (SHALE),	SPT
71							dark brown, very intensely fractured	
							to decomposed, soft, not healed	
72							(Lean Clay (CL), low plasticity)	
73								
74								
75								
		43					← Same	SPT
76		50						

Caltrans | EXPLORATION BORING FIELD LOG | Date 10-15-07 | Boring No. ENB-R2

Location Doyle Drive Replacement | Lab No. | EA No. 163701 | Page 4 of 4

Dist. 04 Co. SF Rt. 101 P.M. | Br. No. | Purpose of Work Geotechnical Investigation

Rt. Ft., Lt. | Line. Sta. | Northings. | Eastings. | Elev.

Ground Water Data: Date / Time | Water Level | Bot. of Boring

Logged By : E Ortega | Drill Crew :

Drill rig : | Hammer Type and Weight :

Drilling Method : Wet rotatory | Casing :

Hole Completion :

Depth	Samples / Interval / Tool	Blows	RQD	Sample I.D.	% Rec.	Strength	Graphic Log	Description			Remarks
77											
78											
79											
80											
81								← Same, with some oxidation spots			
82								RQD = 4+4.5/36 = 23.6%			
83											
84											
85											
86								← Same			
87											
88											
89											
90											← 12-14-07
91											
92											
93											
94											
95											
96								← Same			
97											
98								← Bottom of Boring @ 98' on 12-14-07			

34-0164 SB-R1

Caltrans — EXPLORATION BORING FIELD LOG

Date 8/2C | Boring No.

Location Doyle Dr. | Lab No. | EA No. 163701 | Page 1 of 3

Dist. 04 Co. SF Rt. 101 P.M. | Br. No. | Purpose of Work

Ft.. Lt. Rt. Line. Sta. Northings. Eastings. Elev.

Ground Water Data — Date / Time | Water Level | Bot. of Boring

Logged By : | Drill Crew : Bob Corey Steve Andrews

Drill rig : | Hammer Type and Weight : Automatic

Drilling Method : Rotary Wash | Casing :

Hole Completion : 110 bags Grout To 5 bags Chips to 0.5 bags Grass Plug on Top

Depth	Sampler Interval	Type	Blows/ROD	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Kg	PPM	Remarks
1								Grass w/ Silty Sand Roots			
2					70%			(SP-SM) Silty Gravelly Sand (SW)			
3		Pencil Core						Dry 15% silt 15% Angular Gravel			
4								70% Fine Sand			
5			1/2	1	100%						Sample 1
6								Sand (SP) - 100% med sand No Plasticity			
7								No cementation			
8					100			Sunday Clay (SC) · Very Soft · Green	0-0.5		
9								Gray · 40% sand · 60% Silt · Low Plasticity			
10								No Cement Grades To			B
1		3" Liner	2	2	100			Clay (CL) · Very Soft 100% Gray	0		Sample 2
2								med - High Plasticity Roots &			
3								Grass			Bore hole collapsed
4					100			1" Layer of Sand w/ roots ↓ Grades To			
15								Sand (SP) 100% med sand No Plasticity			
6			1	3				No cementation			Sample 3
7								· Very Loose			
8											
9					100						
20											
1			Liner	4				Same Shells @ 20' med dense			Sample 4
2											
3					70%						
4											
25											
6			1.5D	5				Color Change Yellow Brown			Sample 5
7											
8					70						
9											
30											
1			1.5D	6	100			Sand w/ silt (SW SM) Colma Formation			Sample 6
2			24"					Dense Yellow Orange 10% silt			
3								90% Fine sand No Cementation			
4					70						
35											
6			1.5D	7	100			Colma Same as above			Sample 7
7			15"					Some Laminations			
8											
9											
40											

8/2/08

34-01645B-R4

Caltrans EXPLORATION BORING FIELD LOG

Date 8/26 | Boring No.

Location | Lab No. | EA No. | Page 2 of 2

Dist. Co. Rt. P.M. Br. No. Purpose of Work

Rt. Ft., Lt. Line, Sta. Northings. Eastings. Elev.

Ground Water Data: Date/Time | Water Level | Bot. of Boring

Logged By : | Drill Crew :

Drill rig : | Hammer Type and Weight :

Drilling Method : | Casing :

Hole Completion :

Depth	Sample Interval	Type	Blows/RQD	Sample I.D.	% Rec.	Strength	Graphic Log	Description	KP	RQD	Remarks
1			14 19 26	8	100			Same			Sample 8
2											
3											
4											
45											
6			15 24 26	9	100			Silty Sand (SM) Dense yellowish orange 25% Silt 75% Fine Sand No Plasticity No Cementation			Sample 9
7								@7.8 Feet No Lamination Gray			
8											
9											
50								Sand (SP) Dense 100% med Sand Yell orange			
1			10 16 17	10	100			No Cement			Sample 10
2											
3								@51.25 Silty Sand (SW-SM) Green Gray 40% Silt 60% Fine Sand No Plasticity No Cement			
4											
55											
6			11 15 21	11	100			Some Clay			Sample 11
7								Grade into Sand (SP) Dense Yell Orange			
8								100% med Sand			
9								Clayey Sand (SC) 30% Clay 10% Silt 70% Fine Sand Green No Plasticity			
60								No Cement			
1			9 15 22	12	100			Grades to Sand (SP) Green 100% med Sand			Sample 12
2								Grades to Silty Sand dense Green 30% Silt 70% Fine Sand			
3											
4											
65								Same			
6			9 16 25	13				Clay (CH) Very Stiff Green 100% Clay Med - High Plasticity No Cement	2.75		Sample 13
7											
8											
9											
70								Clasts of Shale in Clay			
1			5 7 10	14				Shale brown laminated 45° Angle up To 1" thick & Sandstone ½" clasts Angular			Sample 14
2								Impressions of shells in shale			Sandstone Pebbles well rounded
3								Clay with shells 70% Clay 30% Shells			
4								Silty Sand (SM) Yellow Orange Red waxy			
75			13 25 40	15	75%			Clayey Sand (SC) Very Stiff 40% Clay 60% Fine Sand Gray sand inclusions	3.45		Sample 15
6											
7										NA	Start Coring
8					20%			Sandstone: Fine grain Thickly bed brown			Run Time
9								Very intense Weathering High fracture		NA	
80								Very hard			

TOP

BH 34 0167SB R1

Caltrans | EXPLORATION BORING FIELD LOG | Date 8/ | Boring No.

Location | Lab No. | EA No. EA163704 | Page 3 of 3

Dist. | Co. | Rt. | P.M. | Br. No. | Purpose of Work

Ft., Rt./Lt. | Line. Sta. | Northings. | Eastings. | Elev.

Ground Water Data: Date/Time | Water Level | Bot. of Boring

Logged By : | Drill Crew :

Drill rig : | Hammer Type and Weight :

Drilling Method : | Casing :

Hole Completion :

Depth	Sample Interval	Tool Blows	RQD	Sample I.D.	% Rec.	Graphic Log	Description	Remarks (Run / Time)
81							Same SST highly decomposed	80 → 84 1:29 → 1:49
2		9/29"		29/48			Sandstone med. Grain · massive	
3							Yellow orange interbedded weather	
4							highly fractured Extremely hard	
85								
6								84 → 88 1:58 → 2:16
7		20/48		48/48			Bedding Plane Fracture 40°	
8								
9								
90								88 → 93 2:22 → 2:42
1		22/60		58/60			Same	
2								
3								93 → 98 2:52 → 3:05
4								
95								
6		16/60		59/60			Graywacke Same Fracture 40°	98 → 100' 3:07 → 3:11
7								
8								
9		17/24		24/24			Same	
100								100' 8/2=6/08
1								
2								
3		9/60		36/60			Graywacke Higher Clay/Silt content	
4							Very Intensly Fractured massive	100' → 105 8:28 → 8:41
105							Hard	
6								
107								
8		0/100		40/60			Same	105 → 110 8:47 → 8:55
9								1:16 → 1:21
110								Hole broke @ 8:55
								repairs begun 1:16
								start Drilling again
							Total Depth 110'	
							Grouted to Surface	
							Chips to 0.5' bgs	
							Replace with Grass with	
							original Grass Plug	
							H.O flowing out of Pipe @ 110'. Pull pipe	
							up 2' Flowing water stops	

34.0164 MB. R 2

Caltrans EXPLORATION BORING FIELD LOG

Date 9/8/08 | Boring No.

Location Marshall & Gorgas St | Lab No. | EA No. 163701 | Page 1 of 3

Dist. 04 Co. SF Rt. 101 P.M. Br. No. Purpose of Work Geotechnical

Ft. Rt. Lt. Line. Sta. Northings. Eastings. Elev.

Ground Water Data: Date / Time | Water Level | Bot. of Boring

Logged By: M Gaffney | Drill Crew: Bob, Karl

Drill rig: Acker | Hammer Type and Weight: Automatic

Drilling Method: Rotary Wash | Casing:

Hole Completion: 120'

Depth	Sample Interval	Tools Blows/Ft	Sample I.D.	% Rec.	Strength	Graphic Log	Description	LP	RQD	Remarks
1							Asphalt 1" of Green Clay			
2							Sand (SP): Green. 100% med sand			
3				75			No Plast No Cement			
4										
5										
6	5.5 Core	1	1	100			Clay (CH) soft. Green (Top 3" 5.5-5.7 black	0.5		Sample 1
7							organic) 100% Clay High Plasticity, NO			
8							Cement			
9										
10										
11	10.5 Core	2	2	100			Sand w/clay (SC) Green 10% Clay 90% Sand			Sample 2
12							Clay again			
13										
14							Sand Green/Gray 100% Sand (coarse w/ depth)			
15							No Cement Smells			
16	15.5 Core	3	3	100						Sample 3
17				30%						
18		Corrosion								
19										9/8/08
20										
21	20.5 Core	4	4	80			Same - SPT Push Under: Tamper			Sample 4
22							Weight			
23				50%						
24		Corrosion								
25							Grade To			Sample 5
26	25.5 Core	5					Clayey Sand (SC) Very loose Gray	.5		Push w/ hammer
27							Green 20% Clay 10% Silt 70%			
28							med grain Sand No Plasticity NO			
29				100			Cement			
30							Sand (SP) Light brown 100% med →			Reach Sand Sample 6
31		6					Coarse Sand. No Cementation			RPM on Hammer 50 FT
32							@ 31.25 - Change in Color Gray Green			strong blows increas-
33							& Fine Grain Sand			ingly tight
34							@ 33. Light Brown. Gray Green Pockets			
35							of Sand 6" (Colored)			
36	35.5 Core	7	7	100			Sand (SP) Very Dense. Yellow Orange			Sample 7
37							Red Lamination 1/2" Thick & Black			
38							Lamination 100% Sand			
39				100						
40							Same			

Adam 818-369-6965

54-D169NB R2

Caltrans | EXPLORATION BORING FIELD LOG | Date | Boring No.

Location | Lab No. | EA No. 163701 | Page 2 of

Dist. | Co. | Rt. | P.M. | Br. No. | Purpose of Work

Ft., Lt. | Rt. Line. Sta. | Northings. | Eastings. | Elev.

Ground Water Data: Date / Time | Water Level | Bot. of Boring

Logged By : | Drill Crew :

Drill rig : | Hammer Type and Weight :

Drilling Method : | Casing :

Hole Completion :

Depth	Sample Interval	Tool	Blows	ROD	Sample I.D.	% Rec.	Strength	Graphic Log	Description	USCS	Qual	Remarks
41	X	10 15 16		18		100			Same Sand (Colma) Dense			Sample 8
42												
43												
44												
45												
46	X	12 21 26		9		100			Same			Sample 9
47												
48									@ 48' red laminations			
49												
50												
51	X	12 25 50		10		100						Sample 10
52												
53									Same			
54												
55												
56	X	9 17 20		11		100			Same			Sample 11
57												
58												
59						90						
60												
61	X	12 18 26		12								Sample 12
62									- color change blue Gray Homogeneous			
63									Out of Colma			
64									Sand (SP) Dense Blue Gray 100%			
65									Fine Sand No cementation			
66	X	11 17 20		13		100						Sample 13
67												
68									Same as above			
69												
70									↓ Grades To			
71	X	8 12		M		100			Sand w/ Silt (SP-SM) Dense brown Gray			Sample 14
72									80% Silt 90% Fine Sand No cement			
73												
74												
75									Clay (CL) brown 100% Clay High Plasticity			
76	X	4 6 9		15					No cement	325-75		Sample 15
77									@ 76' Seashells			At Between 75-85
78												a caller Form above Drill
79									70% Clayey Sand (SC) brown 40% clays 60% Fine sand			Head & Water when in To
80									30% Sandy Clay (CL) " 70% Clay 30% Fine Sand ½"			Formation

Well rounded argillite Pebble 1½" Angular Sandstone Clast

BH#34 - 01-64 N.B. R2

Caltrans EXPLORATION BORING FIELD LOG

Date | Boring No.

Location | Log No. | EA No. 16-3701 | Page 3 of

Dist. | Co. | Rt. | P.M. | Br. No. | Purpose of Work

Rt. Ft., Lt. | Line. Sta. | Northings. | Eastings. | Elev.

Ground Water Data: Date / Time | Water Level | Bot. of Boring (Drill Fluid)

Logged By : | Drill Crew :

Drill rig : | Hammer Type and Weight :

Drilling Method : | Casing :

Hole Completion :

Depth	Sample Interval / Type / Blows / RQD	Sample I.D.	% Rec.	Strength / Graphic Log	Description	qu	Rqd	Remarks
81	7 11 12	16			Clay (CL) Hard Green 100% Clay	>4.5		Sample 16 9/9/08
2					High Plasticity			
3					Sand increasing downward			9/10/08
4								
85					Sandy Clay (CL) Green 60% Clay			
6	5 13 15	17	100		40% Sand No Plast. No Cement	3.5-4.0		Sample 17
7					@ 97' Color Change Yellow Orange			
8					@ 98' Sub Angular 1" Gravel			
9					decomposed → Slightly weathered			
90					↓			
1	4 6 8	18	70		Clayey Sand (SP-SC) medium dense			Sample 18
2					Yellow orange red mottle ; 30% Clay			
3					65% med sand 5% Gravel sub round			
4					½" Gravel No Plasticity No Cement			
95								
6	12 18 20	19	90		Same 50% Clay 50% Med-Fine Sand			Sample 19
7								
8								
9								
100					99.5			
1	10 17 22	20	90		change color Light Gray black mottle			
2					100.5 Color Yellow Orange Light Gray &			Sample 20
3					red mottle 95% Clay 5% Fine to Coarse			
4					Sand - Coarse Quartz sand up to			
105					½ inch			
6	50 50/4	21	20		↓ Quartz sand increased			
7					@ 104.75 Decomposed sandstone			Sample 21
8					Brown			106.5 - 110 10:08 - 10:28
9					Graywacke			106.5 - 108 Hard Drilling
110								108-109 Soft Drilling
1	39 50/5	22	50					109-110 Hard Drilling
2					Sandy Gravel - Gray white Brown			Sample 22
3					Highly Decomposed. Quartz			
4					Graywacke			10:47 - 10:52 for 2ft
115								
6					Total Depth 120'			
7					Drill Ahead			Grout 120' - 5' Tremmie. 22 bag Samples 10:52 - 11:14 112.5 - 120
8					6:1 T			Bentonite chips 5' - 0.5' No Core Boxes
9								Cement 0.5' - 0'
120								Hole PS logged before Grout

Sampling ↑ / ↓ Drilling

No Artesian Conditions were observed

TS-R2

Caltrans EXPLORATION BORING FIELD LOG

Date 1-07-08 | Boring No.

Location Doyle Drive Replacement | Lab No. | EA No. 163701 | Page 1 of 2

Dist. 04 Co. SF Rt. 101 P.M. Br. No. | Purpose of Work Geotechnical Investigation

Rt. Ft. Lt. Line. Sta. Northings. Eastings. Elev.

Ground Water Data: Date / Time | Water Level | Bot. of Boring
1-7-08 (24) | 3' |

Logged By : E. Ortega | Drill Crew : R. Medina

Drill rig : Frasto Multidrill XL | Hammer Type and Weight :

Drilling Method : Wet Rotatory | Casing :

Hole Completion : 1-07-08

Depth	Sample Interval	Tool	Blows	RQD	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Remarks
1									← Drilled thru AC Pavement	
2									FILL	
3										
4										
5			3							MC
6			2		b					
			3		a					
7			0						← Poorly graded Silty Sand (SP),	SPT
			1						loose, dark gray, med. sand, weak cementation,	
8			1						over Sandy Clay (CH), very soft,	
9									dark gray, med. thick, abt. qu = 0.5-1.0 Tsf	
10									(9in SP over 9in CH)	
										Shelby
11										
12			50	psi						
13										
14										
15			6							MC
16			11							
			13		a					
17			8						← Poorly graded Silty Sand (SP),	SPT
			15						medium dense, dark gray, med. sand,	
18			15						weak cementation, with marine shells	
19										
20										
			10							MC
21			20							
			23		a					
22			6						← Same but dense	SPT
			16							
23			23							
24										
25										
			3							MC
26			9							
			6		a					

TS-R2

Caltrans

EXPLORATION BORING FIELD LOG

Date 1-07-08 | Boring No.

Location Doyle Drive Replacement | Lab No. | EA No. 163701 | Page 2 of 2

Dist. 04 Co. SF Rt. 101 P.M. Br. No. Purpose of Work Geotechnical Investigation

Ft.. Rt. Lt. Line. Sta. Northings. Eastings. Elev.

Ground Water Data: Date/Time | Water Level | Bot. of Boring

Logged By : E Ortega | Drill Crew : R Medina

Drill rig : Fraste Multidrill XL | Hammer Type and Weight :

Drilling Method : Wet Rotatary | Casing :

Hole Completion :

Depth	Sample Interval / Tool	Blows	RQD	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Remarks
27		0						Sandy Clay (CH) very soft dark gray, low pls, q_u = 0.5 Ton/ft²	SPT
28									
29									
30									
31		2							MC
		5							
		5		a					
32		7						Poorly graded Clayey Sand (SP-SC), loose, dark gray, med sand, weak cementation, with marine shells	SPT
33		2							
34		4							
35									
		3							MC
36		3							
		4		a					
37		2						Same but medium dense	SPT
38		8							
39		19							
40									
		16							MC
41		13							
		18							
42		3						Poorly graded Silty Sand (SP), loose, dark gray, med. Sand weak cementation.	SPT
		4							
43		4							
44									
45									
		1							MC
46		1							
		1		a					
47		0						Sandy Clay (CH), firm, dark gray med to high pls, q_u = .5 - 1.0 Ton/ft²	SPT
		1							
48		4							
49									
50									
								Poorly graded Silty Sand (SP), very dense dark gray, med sand, weak cementation	MC (Colma Sand ?)
51									

Bottom of boring @ 51.5 on 1-07-08

TS-R3

Caltrans | EXPLORATION BORING FIELD LOG | Date 2-5-08 | Boring No.

Location Doyle Drive Replacement | Lab No. | EA No. 163701 | Page 1 of 3

Dist. 04 Co. SF Rt. 101 P.M. Br. No. | Purpose of Work Geotechnical Investigation

Rt. Ft., Lt. Line, Sta. Northings, Eastings, Elev.

Ground Water Data: Date / Time | Water Level | Bot. of Boring

Logged By: E Ortega | Drill Crew: B Johnson

Drill rig: CME 75 | Hammer Type and Weight:

Drilling Method: Rotatory Wash | Casing:

Hole Completion: 2-5-08

Depth	Sample Interval / Tool / Blows / RQD	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Remarks
1						Drilled thru AC pavement and fill	
2							
3							
4							
5	5					Sandy Clay (CH), stiff, light brown, med to high plas, q_u = 1.5 – 2.0 Ton/ft²	SPT
6	6						
	5						
7							
8							
9							
10	3					Poorly graded Sand (SP), loose, dark gray, med. sand, weak cementation, with tree roots.	SPT
11	3						
	6						
12							
13							
14							
15	15						
16	34					Same but very dense with gravels to 1" and marine shells (1% gravels)	SPT
	49						
17							
18							
19							
20							
21	3					Same	SPT
	12						
	19						
22							
23							
24							
25							
	High					Fat Clay (CH), very soft, dark gray, high plas (Bay Mud)	SPT
26							
27							
28							
29							
30							

TS-R3

Caltrans | EXPLORATION BORING FIELD LOG | Date 2-5-08 | Boring No.

Location Doyle Drive Replacement | Lab No. | EA No. 163701 | Page 2 of 2

Dist. 04 Co. SF Rt. 101 P.M. Br. No. Purpose of Work Geotechnical Investigation

Rt. Ft., Rt. Lt. Line. Sta. Northings. Eastings. Elev.

Ground Water Data: Date / Time | Water Level | Bot. of Boring

Logged By : E Ortega | Drill Crew : B Johnson

Drill rig : B47 | Hammer Type and Weight :

Drilling Method : Rotatory wash | Casing :

Hole Completion : 2-5-08

Depth	Sample Interval	Soil Classification (USCS)	Blows per 6" or RQD	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Remarks
30								← Sandy lean Clay (CL), very soft, dark gray, low plas.	Braggs
31			a - Push						
32									
33									
34									
35			12					← Poorly graded Sand (SP), dense, light brown, med Sand, weak cementation (Colma Sand) w/ some oxidation spots.	SPT
36			20						
37			25						
38									
39									
40			22					← Same but very dense	SPT
41			32						
42			33					← Bottom of boring @ 41.5' on 2-05-08	

RW15-R1

Caltrans EXPLORATION BORING FIELD LOG

Date 2-6-08 | Boring No.

Location Doyle Drive Replacement | Lab No. | EA No. 163701 | Page 1 of 2

Dist. 04 Co. SF Rt. 101 P.M. | Br. No. | Purpose of Work Geotechnical Investigation

Rt. Ft., Lt. | Line. Sta. | Northings. | Eastings. | Elev.

Ground Water Data: Date / Time | Water Level | Bot. of Boring

Logged By : E Ortega | Drill Crew : B Johnson

Drill rig : B47 | Hammer Type and Weight :

Drilling Method : Rotatory Wash | Casing :

Hole Completion : 2-6-08

Depth	Sample Interval (ft)	Blows per 6"	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Remarks
1							← Drilled thru AC pavement and fill	
2								
3								
4								
5		3					← Poorly graded Sand (SP), loose, dark brown, med sand, weak cementation, with gravels to 1" (85% Sand 15% gravels)	SPT
6		3						
7		4						
8								
9								
10								
11		3					← Poorly graded Sand (SP), med dense, dark gray, med sand, weak cementation	SPT
12		6						
13		11						
14								
15								
16		5					← Same	SPT
17		11						
18		14						
19								
20								
21							← Sandy Fat Clay (CH), very soft, dark gray, med to high plas, q_u = 0.25 - .50 Ton/ft²	SPT
22		Push						
23								
24								
25								
26		7					← Poorly graded Sand (SP), med dense, dark gray, med sand, weak cementation.	
27		12						
28		12						
29								
30								
31								
32								
33								
34								
35								

RW15-R1

Caltrans | EXPLORATION BORING FIELD LOG | Date 2-6-08 | Boring No.

Location Doyle Drive Replacement | Lab No. | EA No. 163701 | Page 2 of 2

Dist. 04 Co. SF Rt. 101 P.M. Br. No. Purpose of Work Geotechnical Investigation

Rt. Ft., Lt. Line, Sta. Northings. Eastings. Elev.

Ground Water Data: Date/Time | Water Level | Bot. of Boring

Logged By: E Ortega | Drill Crew: B Johnson

Drill rig: CME 47 | Hammer Type and Weight: | Casing:

Drilling Method: Rotetory wash

Hole Completion: 2-6-08

Depth	Sample Interval (Tool)	Blows/ROD	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Remarks
30							← Sandy fat Clay (CH), very soft, dark gray, med to high pls, q_u = 0.75 Tsf/ft2	SPT
31								
32								
33								
34								
35		4					← Poorly graded Sand (SP), dense, dark, gray to light brown, mod sand, weak cementation, some oxidation spots (Colma Sand)	SPT
36		16						
37		16						
38								
39								
40								
41		17					← Same but very dense and dark gray.	SPT
42		30						
43		30						
44								
45								
46		17					← Same	SPT
47		24						
48		31						
49								
50								
51		24					← Same but light brown	
52		>50						
53							← Bottom of boring @ 51.5' on 2-6-08	