

California Test 331
September 1998

2. Report the percentage of residue by evaporation as the average of the results from the three containers.

REFERENCES:

California Test 332, California Test 401
AASHTO Designation T-59

End of Text (California Test 331 contains 2 pages)

E. SAFETY AND HEALTH

Prior to handling, testing or disposing of any waste materials, testers are required to read: Part A (Section 5.0), Part B (Sections:5.0, 6.0 and 10.0) and Part C (Section 1.0) of Caltrans Laboratory Safety Manual. Users of this method do so at their own risk.